

## Donaldson Torit (DCE) Unimaster UMA 254 G8 Dust Extractor

**Sorry, this machine is no longer available**

We might be able to meet your requirements with other [Dry Dust Filters](#) machines.



Stock No	<a href="#">ET1306</a>
Manufacturer	<a href="#">Donaldson Torit (DCE)</a>
Model	UMA 254 G8
Serial	181759
Approx Duty CFM / M <sup>3</sup> /Hr	2000 // 3400
Filter Area ft <sup>2</sup> / m <sup>2</sup>	250 // 25
Other Info	DCE's most powerful 250 series extractor
Weight (kgs)	300kgs
External Dimensions (WxDxH mm)	1450 x 940 x 2750mm

### Description

A second hand DCE Unimaster UMA 254 G8 dust extraction unit designed to stand alongside a very wide range of dust generating machinery and processes.



The UMA 252 is a compact, self contained fabric filter dust control unit complete with a 5.5 kW fan, self cleaning mechanism, explosion relief panel, easy-access filter assembly, & a 4ft3 waste container bucket with quick-release sealer gear

#### Design features

- Compact Design

Minimises floor space and fits in virtually any plant layout.

- Versatility

To suit a variety of dust collection applications

- Quiet & Efficient Operation

Motors and fan are enclosed in collector housing to minimise noise.

- Waste storage

Large 4ft3 collection bucket

- Explosion relief panel

Allows for the use with potentially explosive dust covered under the ATEX regulations

- Quick-Release Lever mechanism

Allows for easy removal and maintenance of waste storage bin

- Silencer box

Reduces noise levels in the environment.

- Inlet Deflector

Knocks down larger particles into the hopper reducing bag abrasion and increasing bag filter life.

- Heavy-duty flexible metal inner bag coils

Inserted into filter bags which keeps the bag envelopes open to maximize airflow and assist in knocking dust off during cleaning cycle.

- Bag-Release Screws

Allow for easy removal of bags.

Electrical supply 400v/ 3ph / 50Hz / 5.5kw

The Marketplace for Surface Technology.  
New and Used Process Equipment & Machinery.  
*Machine Datasheet*



Photographs taken prior refurbishment. Our refurbishment service is not available on all machines.